



Digital Clamp Meter VC606A VC606B VC606C

This test meter is a handheld automatic range digital clamp meter which is driven by battery. The clamp multimeter can be used to measure such parameters as DCV, ACV, ACA, Resistance, Continuity Buzzer, Diode, Frequency, Temperature, etc. This LCD Digital AC/DC clamp multimeter is a portable and professional clamp meter which has almost everything you need for a full multimeter. Digital clamp meter is widely used for field, laboratory, shop and home applications.



FUNCTION	RANGE	606A	606B	606C
ACV	2V/20V/200V	±(0.8%+10)		
	400mV/4V/40V/400V		±(0.8%+10)	
	4V/40V/400V			±(0.8%+10)
	600V	±(1.0%+10)	±(1.0%+10)	±(1.0%+10)
DCV	200mV/2V/20V/200V	±(0.5%+4)		
	400mV/4V/40V/400V		±(0.5%+4)	±(0.5%+4)
	600V	±(1.0%+6)	±(1.0%+6)	±(1.0%+6)
RESISTANCE	200Ω/2kΩ/20kΩ/200kΩ/2MΩ	±(1.0%+5)		
	400Ω/4kΩ/40kΩ/400kΩ/4MΩ		±(1.0%+5)	±(1.0%+5)
	20 MΩ	±(1.2%+10)		
	40 MΩ		±(1.2%+10)	±(1.2%+10)
ACA	2A/20A	±(2.5%+8)		
	4A/40A		±(2.5%+8)	
	40A/600A			±(2.5%+8)
	200A/600A	±(2.5%+8)		
	400A/600A		±(2.5%+8)	
CAPACITANCE	2nF/20nF/200nF/2uF/20uF/1000uF	±(5.0%+8)		
	4nF/40nF/400nF/4uF/40uF/1000uF		±(5.0%+8)	±(5.0%+8)
FREQUENCY	0-10MHz		±(0.3%+3)	±(0.3%+3)
DCA	40A/600A			±(2.5%+8)
TEMPERATURE	-20°C~400°C -4F-752°F		±(3.0%+2)	
DIODE TEST		V	V	V
CONTINUITY TEST		V	V	V
DATA HOLD		V	V	V
LOW BATTERY INDICATOR		V	V	V
AUTO POWER OFF		V	V	V
OVERLOAD PROTECTION		V	V	V